

RoSPA Report June 2021

Equipment	Risk Level	Risk Score	Description	Remedial Tasks	Action
Swing Barriers	Low	5	Paintwork in poor condition	Descale and repaint	
Cricket Square	Medium	8	Cricket square too close to play area	Play area closed when cricket in play	No further action
Gate to Roadside	Medium	8	Hard or sharp projections	Replace ball on end of gate latch	
General Surface	Low	7	Surface is uneven	Build up ground levels	
Climbing Frame	Medium		As low as possible	No remedial tasks	
Log Train	Low	2	Natural splits in wood	Monitor for splits exceeding 8mm	Monitor
Slide Safer Surface	Low	7	Edges of safer surface curling/shrunk	Modify to prevent trip hazard	
Slide Safer Surface	Low	6	Surface has unintended grass, moss,weeds	Remove	
Swing Chains	Low	7	Some chain wear	Monitor for further deterioration	Monitor
Swing Frame	Medium	8	Item is rusting in places	Repair at top of frame	
Swing Support	Low	7	Insufficient distance between seat & support	No reasonably pracicle action is identified	No further action

Swing Height	Medium	8	Free height of fall exceeds the max permitted	Consider extending safer surface	
Swing Safer Surface	Medium	8	Safer surface has hard edging	Consider extending/removing safer surface	