

RoSPA Report June 2019

Remedial Action

- 1) Cricket Square (medium risk - 8)
Cricket square too close to play area
No further remedial action (play area closed when cricket being played)
- 2) Gate to field (low risk - 7)
Risk of entrapment on side of gate
Adjust gate & post / fit new rubber buffer to ensure a spacing of at least 12mm throughout
Action - Requested quotation from Horsham Fencing
- 3) Gate to road (medium risk – 8)
Loose in ground
Install new post
Action - Requested quotation from Horsham Fencing
- 4) General Surface (low risk – 7)
Uneven surface / trip hazard
Build up surface (CC to provide soil to build up surface)
Actioned 5th October 2019 – No further remedial action
- 5) Climbing Frame (medium risk)
No remedial action
- 6) Swings (medium risk -7)
Rusting in places (at top of frame joints)
Action - Repair
- 7) Swings (medium risk – 8)
Free height of fall exceeds the maximum permitted of 3 metres
Consider extending the surfacing
Action - Repair
- 8) Swings (medium risk – 8)
The safer surface has hard edging
Remove edging when surface is levelled
Action – remove edging