

## RoSPA Report June 2020

### Remedial Action (updated July 2020)

- 1) Cricket Square (medium risk - 8)  
Cricket square too close to play area  
**No further remedial action (play area closed when cricket being played)**
- 2) Gate to field (low risk - 5)  
Risk of entrapment on side of gate  
Adjust gate & post / fit new rubber buffer to ensure a spacing of at least 12mm throughout  
**Action – Completed, Horsham Fencing carried out remedial works – 30<sup>th</sup> June 2020**
- 3) Gate to road (medium risk – 8)  
Loose in ground  
Install new post  
**Action – Completed, Horsham Fencing carried out remedial works – 30<sup>th</sup> June 2020**
- 4) General Surface (low risk – 7)  
Uneven surface / trip hazard  
Build up surface  
**Action – Monitor, one small mole hill**
- 5) Log Train (low risk - 6)  
Natural splits / shakes in timber  
**Action – Monitor**
- 6) Slide Wet Pour Surface (low risk – 6)  
Surface has grass/moss/weeds  
**Action – Completed, surface cleaned 12<sup>th</sup> July 2020.**
- 7) Swing Seats (low risk -7)  
Bird Fouling on swing seats  
**Action – Completed, seats cleaned 9<sup>th</sup> July 2020.**
- 8) Swing Frame (low risk – 7)  
Frame rusting in places (top joints)  
**Action – Monitor, cosmetic, no physical defect**
- 9) Swing Wet Pour Surface (medium risk – 8)  
Free height of fall exceeds the maximum permitted of 3 metres  
Consider extending the surfacing  
**Action – Monitor, re-assess when new facilities are planned.**
- 8) Swing Wet Pour Edging (medium risk – 8)  
The safer surface has hard edging / foundation within the impact area  
Consider extending surfacing (and/ or removing existing edging)  
**Action – Monitor, re-assess when new facilities are planned.**