

	Check	Action Required (tick if ok)	Date completed
Barriers - Swing	Are they stable and with the paintwork in a good condition	ok	30/12/20
Cricket Square	Is the square in a good condition and with little weed present	yes	
Gates	Do the gates operate correctly	yes	
	Are there no finger entrapments or damage	no	
Fencing	Are all panels present, undamaged and secure	yes	
General Surfaces	Are they free of litter, glass and fouling	yes	
	Is it free of trip hazards to the edges	yes	
Litter Bins	Are they secure with liners present	yes	
	Are they empty or not in need of emptying	ok	
Signage	Are they secure, undamaged and legible	yes	
Seating - Mixed	Are the seats secured to the ground, stable, undamaged and clean	yes	
Climber – Frame - Ladder	Are the supports and climbers secure and free from damage and any obvious signs of corrosion	yes	
	Is the safer surfacing undamaged, free from trips and slippery algae	yes	
Play Train	Is the unit clean, secure with no obvious signs of decay and with all component parts present and in a good condition	yes	
	Is the safer surfacing undamaged and free from trips	yes	
Carousel - Rocker	Does the unit revolve smoothly with no undue noise	yes	
	Are all component parts secure and free from damage	yes	
	Is there no damage to the seat and top plate	ok	
	Is the safer surfacing undamaged, free from trips and slippery algae	yes	
Slide	Are the supports and steps secure, free from damage and any obvious signs of corrosion	yes	

	Is the slide-chute clean and free from any foreign objects and with no sharp edges to the side panels	yes	
	Is the safer surfacing undamaged, free from trips and slippery algae	yes	
Swing Mixed - 2 Bay 2 Junior 2 Toddler Seat	Are all supports and the top-bar secure and undamaged and free from any obvious signs of corrosion	yes	
	Are the swing seats free from damage and secure	yes	
	Are the chains and shackles showing no signs of excessive wear and working freely	yes	
	Is the safer surfacing undamaged, free from trips and slippery algae	yes	

General comments:

AREA SOMEWHAT MUDDY ESPECIALLY BY GATE TO LARGE AREA

Name of Inspector	N Bryant		
Date of Inspection	30/12/20		
Signature of Inspector			